
BELL HELICOPTER TEXTRON FORT WORTH TX

CONCEPTUAL DESIGN OF A HELICOPTER COMPOSITE TRUSS TAIL BOOM, (U)

DAM51-78-C-0016 AD-A085 132 F/G 1/3 USAAVRADCOM-TR-80-D-8 UNCLASSIFIED NL 1.2 A: 28:18:



USAAVRADCOM-TR-80-D-8



CONCEPTUAL DESIGN OF A HELICOPTER COMPOSITE TRUSS TAIL BOOM

David A. Gallian
BELL HELICOPTER TEXTRON

P. O. Box 482
Fort Worth, Texas 76101

April 1980 April 1980 Final Report



Approved for public release; distribution unlimited.

Prepared for

APPLIED TECHNOLOGY LABORATORY

U. S. ARMY RESEARCH AND TECHNOLOGY LABORATORIES (AVRADCOM)

Fort Eustis, Va. 23604

80 6 5 04 6

200 P. A.

APPLIED TECHNOLOGY LABORATORY POSITION STATEMENT

This report was prepared by Bell Helicopter Textron under the terms of Contract DAAK51-78-C-0016. Objectives of this effort were to establish design criteria, design, investigate manufacturing techniques, fabricate, and ballistically test a composite truss tail boom section comparable to an OH-58 tail boom.

Results of this effort show that a satisfactory design was achieved and a filament winding manufacturing technique was developed and used to fabricate the specimens. The specimen met the structural requirements of the comparable tail boom and proved to be ballistically tolerant to the small High-Explosive threat.

The conclusions contained herein are concurred in by the Applied Technology Laboratory. This concurrence is limited to technical accomplishment and does not imply the practicality of the proposed approach for application to current Army aircraft.

The technical monitor for this contract was Mr. George T. Mc-Allister, Aeronautical Systems Division.

DISCLAIMERS

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

When Government drawings, specifications, or other data are used for any purpose other than in connection with a definitely related Government procurement operation, the United States Government thereby incurs no responsibility nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission, to manufacture, use, or sell any patented invention that may in any way be related thereto.

Trade names cited in this report do not constitute an official endorsement or approval of the use of such commercial hardware or software.

DISPOSITION INSTRUCTIONS

Distroy this report when no longer needed. Do not return it to the originator.

Unclassified SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered) READ INSTRUCTIONS
BEFORE COMPLETING FORM REPORT DOCUMENTATION PAGE 3. RECIPIENT'S CATALOG NUMBER PORT NUMBER 2. GOVT ACCESSION NO. ADAG85 13: USAAVRADCOM TR-80-D-8 TYPE OF REPORT & PERIOD COVERED CONCEPTUAL DESIGN OF A HELICOPTER COMPOSITE TRUSS TAIL BOOM . ORT NUMBER AUTHOR(s) B. CONTRACT OR GRANT NUMBER(#) David A. Gallian DAAK51-78-C-8916 9. PERFORMING ORGANIZATION NAME AND ADDRESS Bell Helicopter Textron P. O. Box 482 249 EK Fort Worth, Texas 11. CONTROLLING OFFICE NAME AND ADDRESS SEPORT DATE Applied Technology Laboratory, U. S. Army Research and Technology Laboratories (AVRADCOM) Fort Eustis, Virginia
14. MONITORING AGENCY NAME & ADDRESS(## different from Co. 15. SECURITY CLASS, (of 6 Unclassified 15a, DECLASSIFICATION/DOWNGRADING SCHEDULE 16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited. 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) 18. SUPPLEMENTARY NOTES 19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Composite Helicopter Tail Boom Truss

IG. ABSTRACT (Continue on severee able H necessary and Identify by block number)

This report presents the results of a conceptual study of a helicopter composite truss tail boom. The study included the following tasks: design criteria, material properties, truss design and analysis, manufacturing techniques, and fabrication and ballistic testing. The results of the study indicate that a composite truss is a viable concept for a ballistically tolerant tail boom.

DD 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OBSOLETE

Ballistic Tolerant

Unclassified

SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

054200

Local

A CONTRACTOR

TABLE OF CONTENTS

	Page
LIST OF ILLUSTRATIONS	4
LIST OF TABLES	6
INTRODUCTION	7
DESIGN CRITERIA	9
DETERMINATION OF MATERIAL PROPERTIES	10
DESIGN AND ANALYSIS	14
FABRICATION	49
BALLISTIC TESTING	52
STATIC LOAD CORRELATION	68
DYNAMIC LOAD IMPULSES	79
CONCLUSIONS AND RECOMMENDATIONS	82
REFERENCES	84
APPENDIX A ~ COMPOSITE TAIL BOOM TESTS	85

LIST OF ILLUSTRATIONS

<u>Figure</u>		Page
1	Coupon Fabrication Mandrel	. 12
2	Truss Configurations 4T and 4T/C	. 16
3	Truss Configurations 5T and 5T/C	. 17
4	Truss Configurations 6T and 6T/C	. 18
5	Truss Configurations 7T and 7T/C	. 19
6	Truss Configurations 8T and 8T/C	. 20
7	NASTRAN Model Stiffness Correlation	. 21
8	Typical Damage State 2	. 23
9	Deflection - Configuration 4T	. 24
10	Deflection Damage - Configuration 4T/C	. 25
11	Deflection - Configuration 5T	. 26
12	Deflection - Configuration 5T/C	. 27
13	Deflection - Configuration 6T	. 28
14	Deflection - Configuration 6T/C	. 29
15	Deflection - Configuration 7T	. 30
16	Deflection - Configuration 7T/C	. 31
17	Deflection - Configuration 8T	. 32
18	Deflection - Configuration 8T/C	. 33
19	Configuration Characteristics	. 35
20	Member Joint Testing	. 39
21	Member Joint Specimen After Failure	. 40
22	Member Joint Geometry	. 40
23	Machined Attachment Fitting	. 41
24	Welded Attachment Fitting	. 43

<u>Figure</u>		Page
25	Truss Boom Weight Comparison	44
26	Final Truss Design	45
27	Pinned End Rigid Bars	48
28	Wooden Tooling Pattern	50
29	Sand Casting Mold	50
30	Sand Casting	51
31	Wet Lay-Up	51
32	Truss Loading Diagram	53
33	Load Application Frame	54
34	Targeted Impact Area, Specimen 1	55
35	Exit Side Damage, Specimen 1	56
36	Individual Member Damage, Specimen 1	57
37	Boom Deflection After Impact, Specimen 1	58
38	Targeted Impact Area, Specimen 2	58
39	Projectile Entry Hole, Specimen 2	59
40	Exit Side Fragment Damage, Specimen 2	60
41	Exit Side of Entry Hole, Specimen 2	61
42	Individual Member Damage, Specimen 2	62
43	Boom Deflection After Impact, Specimen 2	63
44	Targeted Impact Area, Specimen 3	64
45	Fragment Damage, Specimen 3	65
46	Upper Tension Longeron, Specimen 3	66
47	Typical Fragment Damage	67
48	Strain Gage Locations, Specimen 1	69
49	NASTRAN Loads, Member 1, Specimen 1	71

Figure		Page
50	NASTRAN LOADS, Member 4, Specimen 1	73
51	Strain Gage Locations, Specimen 2	76
52	Strain Gage Locations, Specimen 3	77

LIST OF TABLES

<u>Table</u>		Page
1	Resin System Properties, LRF-092	10
2	Summary of Material Properties	13
3	Truss Configuration Descriptions	15
4	Preliminary Sizing Study Results	34
5	Member Column Buckling Test Results	37
6	Member Joint Test Loads	39
7	Attachment Fitting Test Results	42
8	Finite Element Section Properties	47
9	NASTRAN Predicted Member Buckling Allowables .	48
10	Specimen Applied Loads	52
11	Correlation of Member Loads Before Ballistic Impact - Test 1	68
12	NASTRAN Member Forces and Moments	70
13	Correlation of Member Loads Before Ballistic Impact - Test 2	75
14	Correlation of Member Loads Before Ballistic Impact - Test 3	78
15	Dynamic Impulse Strain, Test 1	80
16	Dynamic Impulse Strain, Test 2	81

INTRODUCTION

Military activities in the past ten years have subjected the helicopter to increased exposure of air defense measures. The vulnerability of helicopters has increased due to the larger caliber weapons that may be encountered when performing air mobility missions in mid-intensity warfare. Reducing helicopter vulnerability is a major factor in improving helicopter combat effectivenss. Attrition analysis performed by the Army shows that tail boom damage could be a significant contributor to helicopter combat loss.

The primary threat to the helicopter tail boom is an HEI delayed-fuse round. Basically, the fuse is activated upon contact with the structure and detonates after some finite time delay. The combined effect of the fragmentation and the high blast pressure associated with the detonation can cause catastrophic structural failure when occurring within a confined volume such as that found in a conventional tailboom.

An attempt to reduce the vulnerability of very small diameter tail booms would mean an excessive weight increase and/or a large modification cost.

To determine a methodology for the solution to the tail boom vulnerability problem, the design options available to the aircraft designer are monocoque, semimonocoque, or truss. Both the monocoque and semimonocoque are standard methods of aircraft construction. Since each completely encloses a volume, they are more vulnerable to the HEI threat than an open truss design. When the HEI comes into contact with the surface of a conventional tail boom, its fuse is activated and detonation occurs within the confined volume. The resulting fragments and pressure on the structure generally cause extensive damage.

The truss has many vulnerability reduction advantages.

Because of the openness of the truss, the projectile could simply pass through the tail boom without being activitated. If a hit does occur, there is an equal probability of the round striking a member on the exit as on the entrance side of the tail boom envelope. If the hit occurs on the exit side, the round, because of the time-delay fuse, would detonate outside the envelope and cause little damage. If the hit occurs on the entrance side, the blast pressure is vented through the truss and damage is greatly reduced.

Another advantage of a truss is that it can be designed with alternate load paths (or redundancy) by providing additional secondary members.

Potentially, the most important characteristic of an open truss design is that it is insensitive to threat velocity and size of the threat. Thus, when new and larger threats are encountered in the future, the open truss design will not become obsolete.

Additional advantages can be realized from an open truss design if the truss is constructed from composite materials. Composites have relatively high ballistic tolerance, have high specific strength and stiffness (which will allow a high level of redundancy for minimum weight), and are relatively corrosion free. All these directly contribute to reduced weight and maintainability.

A truss constructed from composite materials also lends itself to automatic fabrication through the use of filament winding techniques.

In September of 1978, the Applied Technology Laboratory, Fort Eustis, Virginia, awarded a contract to Bell Helicopter Textron to design and build three composite truss tailboom specimens.

The effort was divided into five separate tasks: design criteria, material properties, truss design and analysis, manufacturing techniques, and fabrication and ballistic testing.

This report presents the results of this study and the conclusions reached after analysis of the results.



DESIGN CRITERIA

The design criteria established for the truss tail boom test section are as follows:


- 1. Truss specimens shall be of sufficient size, that is an envelope not greater than 15 inches in diameter by a length of 60 inches, to evaluate the effects of damage due to a 23mm HEI projectile.
- 2. Test section will be able to carry design limit loads before sustaining any damage. The stiffness of the test section will be comparable to the stiffness of a Model OH-58 tail boom before sustaining any damage.
- 3. After sustaining damage, the test section will be capable of carrying loads that would be developed during a lg high-speed level flight condition. Deflections resulting from the application of these loads to the damaged section will not be of such magnitude as to exceed the allowable driveshaft cocking angle.

Damage criteria will be as follows:

1. A compression side longeron joint and one opposite diagonal member will be considered ineffective.

Should the damage criterion above prove to be too severe, then the alternate damage criteria will be,

2. A compression longeron and one opposite diagonal will be considered ineffective.





DETERMINATION OF MATERIAL PROPERTIES

T/300 graphite with a 280-degree cure adhesive was used for construction of the truss specimens. Although the properties of Union Carbide Corporation's Thornel 300 carbon fiber are well documented, its properties, when combined with an adhesive matrix suitable for use with filament winding techniques, are not. Prior to final analysis of the truss specimens, tension, compression, and shearing strength tests were performed to determine the mechanical properties of the graphite and adhesive mixture.

The resin system selected for use in the fabrication of the truss specimens, LRF-092,* is comprised of Epon 828 resin, MNA hardener, and BDMA accelerator. This resin system is particularly well suited for filament winding fabrication techniques.

The physical properties of this resin system, as measured in the Brunswick Corporation's material laboratory, are shown in Table 1.

TABLE 1. RESIN SYSTEM PROPERTIES, LRF-092

Tensile Strength, psi	8,477
Tensile Modulus, psi x 106	.424
Percent Elongation	3.1
Compressive Strength, psi	16,458
Compressive Modulus, psi x 10 ⁶	.560
Flexural Strength, psi	17,799
Flexural Modulus, psi x 106	.395
Shear Strength, ppsi	7,863
Thermal Expansion Coefficient, in./in.°F	2.98 x10 ⁻⁵
Density, lb/in. ³	.044
Cure Shrinkage, in./10 in.	.067

^{*} LRF-Lincoln Resin Formula, a product of Brunswick Corporation, Lincoln, Nebraska.

In order to obtain test coupons that would be representative of the completed truss specimens, a rectangular steel mandrel was fabricated for filament winding of the coupons. Slots were machined into one end of the mandrel to aid in the fabrication of constant cross-section coupons. The mandrel is depicted in Figure 1. The test coupons were filament wound using a graphite/adhesive mix identical to the mixture that would be used to fabricate the truss specimens. The longitudinal, compression, tension, and shear coupons were prepared from the material wound into the mandrel slots. Transverse coupons were made from the panels wound on the straight section of the mandrel.

Tension specimens were prepared as 1 inch wide x 9 inches long straight-sided coupons with metal tabs bonded on each end. The coupons were loaded axially in a Satec Testing Machine, and strains were monitored using a strain transducer.

Longitudinal and transverse compression tests were performed per ASTM 695-69.

Horizontal shear strength was evaluated using procedures outlined in ASTM D 2344-72.

The results of these tests are summarized in Table 2. Values obtained by averaging the results of six coupons for each test type are tabulated and compared with published results from the Air Force Material Laboratory Design Guide. 1

The state of the s

ADVANCED COMPOSITE DESIGN GUIDE, Rockwell International Corporation, Contract F33615-74-C-5075, Air Force Flight Dynamics Laboratory, Air Force Systems Command, Wright-Patterson Air Force Base, Ohio, April 1976.




Figure 1. Coupon Fabrication Mandrel

TABLE 2. SUMMARY OF MATERIAL PROPERTIES (THORNEL 300/LRF-092)

	Brunswick	AFML*
Longitudinal Tension		
Strength, psi x 10 ³	185.4	180.0
Modulus, psi x 10 ⁶	18.88	19.0
Longitudinal Compression		
Strength, psi x 10 ³	116.70**	180.0
Modulus, psi x 10 ⁶	18.37	19.0
Traverse Tension		
Strength, psi x 10 ³	4.62	5.0
Modulus, psi x 10 ⁶	2.62	1.5
Traverse Compression		
Strength, psi x 10 ³	22.88	25.0
Modulus, psi x 10 ⁶	1.53	
Short Beam Shear, psi	10.77	11.5

^{*} Published results from Air Force Material Laboratory
Design Guide for High Strength Graphite in an Epoxy
Resin.1

** All specimens had premature edge failure.

DESIGN AND ANALYSIS

Phase one of the design and analysis task was to determine the best truss configuration. Truss configurations were judged on the basis of weight, deflection after impact, increase in longeron and diagonal load after impact, the amount of open area, and various manufacturing considerations. Of the configurations studied, all designs which required internal bracing to support the frame members were rejected due to manufacturing considerations. The use of filament-winding techniques requires that a solid winding mandrel be used. The use of such a tool eliminates the possibility of including any internal members in the truss design. With the elimination of all internal bracing, only those configurations incorporating frame members with bending continuity could be considered further.

Those truss configurations chosen for further investigation are shown in Table 3 and Figures 2 through 6.

These ten truss configurations were sized to match the stiffness of the existing Model OH-58 tail boom. The configurations were sized such that the stiffness (as measured by the deflection of a point in the center of the truss frames) of each configuration closely matched that of the first 60 inches of the existing Model OH-58 boom. This stiffness correlation is shown in Figure 7.

To aid in this preliminary sizing and to determine each configuration's deflection characteristics after ballistic impact, a NASTRAN (Reference 2) finite element model of each truss configuration was constructed.

A finite element generator program was written to aid in this task. Basic input consisted of geometry definition at the forward and aft end of the truss section; longeron, diagonal, and frame properties for each bay; and the number of bays. A complete, ready-to-run NASTRAN model was output. Computer time expended per truss configuration generated was less than l second.

Results of the preliminary sizing efforts and the deflection characteristics of the various configurations after ballistic impact are shown in Figures 8 through 18. Shown with each undamaged stiffness plot is the deflection exhibited after

McCormick, Caleb W., NASA SP-222(03) NASTRAN USER'S MANUAL, National Aeronautics and Space Administration, Washington, D.C., July 1978

TABLE 3. TRUSS CONFIGURATION DESCRIPTIONS

	_		Configuration I.D.
4	Lo	ngeron Truss	
	-	Diagonals capable of taking tension only	4 T
	-	Diagonals capable of taking tension and compression	4 T/C
5	Lo	ngeron Truss	
	-	Diagonals capable of taking tension only	5 T
	-	Diagonals capable of taking tension and compression	5T/C
6	Lo	ngeron Truss	
	-	Diagonals capable of taking tension only	6 T
	-	Diagonals capable of taking tension and compression	6T/C
7	Lo	ngeron Truss	
	-	Diagonals capable of taking tension only	7 T
	-	Diagonals capable of taking tension and compression	7 T /C
8	Lo	ngeron Truss	
	-	Diagonals capable of taking tension only	8 T
	-	Diagonals capable of taking tension and compression	8T/C

Variable.




Figure 2. Truss Configurations 4T and 4T/C




Figure 3. Truss Configurations 5T and 5T/C




Figure 4. Truss Configurations 6T and 6T/C




Figure 5. Truss Configurations 7T and 7T/C





Figure 6. Truss Configurations 8T and 8T/C



NASTRAN Model Stiffness Correlation

Figure 7.

application of the two damage criteria. Damage state one refers to the loss of a single longeron and one opposite side diagonal member. Damage state two refers to the loss of a longeron joint and one opposite side diagonal member. Both the longeron and joint were removed from the compression side of the loaded truss model. A 1.5-degree slope line is also included on each graph. This line represents the maximum allowable tail rotor driveshaft coupling misalignment angle.

After each configuration was sized for stiffness, the mass generator in NASTRAN was used to calculate the weight of each truss configuration. A mass density of .056 lb/in.³ was used in this calculation. The weight used for comparison purposes was for the truss only and did not include any provisions for end fittings.

The amount of open area was based on the following assumed member geometry:

- All longerons had 1-inch flanges
- All diagonals had .5-inch flanges
- All frames had 1-inch flanges

The amount of open area presented by a particular truss configuration was calculated as

(circumferential area - member area).

Ballistically induced dynamic impulse loads were felt to be a significant yet unknown design input. It was assumed that the truss configuration that exhibited the smallest change in static longeron and diagonal load after impact would be the configuration that would be less susceptible to large dynamic impulses. Using the NASTRAN models, individual member loads were tabulated for the various truss configurations both before and after the removal of a longeron joint.

As shown in Figure 9, truss configuration 4T exceeded the deflection criterion after damage. Configuration 7T was eliminated from further consideration because of an inability to converge on a tension-only solution. In order to match the stiffness of the existing Model OH-58 boom, both 8 longeron configurations required such a small diameter boom that they approached becoming a solid tube. Both of these configurations were eliminated from further consideration because of this condition. The results from the preliminary sizing study for the remaining six truss configurations are shown in Table 4.









Figure 8. Typical Damage State 2















TO THE PARTY OF TH





A SHEET STATE OF








TABLE 4. PRELIMINARY SIZING STUDY RESULTS

	CONFIGURATION					
	4T/C	5T/C	<u>5T</u>	6T/C	6T	7T/C
WEIGHT, LB/50 in.	3.76	7.66	9.81	7.96	10.29	8.94
% OPEN AREA	67	56	56	48	48	32
DEFLECTION AFTER IMPACT (DAMAGE STATE 2), IN. $(\Delta Y^2 + \Delta Z^2)^{1/2}$.457	.339	.595	.309	.316	.281
% CHANGE IN LONG- ERON LOAD AFTER IMPACT	109	83	60	46	33	26
% CHANGE IN DIA- GONAL LOAD AFTER IMPACT, LB	109	86	254	20	236	38

The key parameters of weight, amount of solid area, deflection after ballistic damage, and increase in longeron and diagonal load after damage are graphically compared in Figure 19. In this chart, the maximum values in each category are plotted as 100 percent. Lesser values are then shown as a percentage of the maximum values. As would be expected, the amount of solid (or presented) area is greater for those configurations having a larger number of longerons.

Likewise, the weight is generally less for those configurations having the fewer longerons.

The configurations that used diagonal members capable of taking only a tensile load were judged to be the worst overall designs. They were heavier than their tension/compression diagonal counterparts and exhibited a large increase in diagonal load after damage. During the initial sizing of these configurations, it became readily apparent that the stiffness of these two configurations was a function of the applied load. Since the stiffness of the existing Model OH-58 boom is constant throughout the range of design loads, any design that does not exhibit such a constant stiffness could possibly pass through a critical frequency as various flight loads were applied. For these reasons, truss configurations 5T and 6T were elminated from the design selection.




Figure 19. Configuration Characteristics

Configuration 4T/C exhibited a deflection pattern after the removal of a longeron joint that came very close to exceeding the 1.5-degree deflection limit. The remaining longerons also had the largest change in static load after damage. Even though configuration 4T/C was the lightest of the proposed designs and had the largest amount of open area, the potential for exceeding the tail rotor driveshaft bearing misalignment angle and the possible large dynamic impulse loads in the remaining longeron members eliminated configuration 4T/C from consideration.

Of the remaining three designs, configuration 6 T/C exhibits the best overall characteristics. The amount of solid area is only slightly higher than 5T/C and is 33 percent less than 7T/C. Configuration 6T/C exhibits a relatively small amount of increased deflection after the loss of a longeron joint. It offers only one-half of the longeron load redistribution of configuration 5T/C and only one-third of the diagonal load redistribution. Manufacturing studies indicate that it would be significantly easier (and thus less expensive) to build a configuration having an even number of longerons. For these reasons, configuration 6T/C was chosen as the best overall truss design. It should be noted that none of the original truss designs were optimized for weight or any other design parameter. The characteristics used for the configuration selection are believed to be representative of their respective designs but should not be considered the best obtainable. The selected truss configuration was optimized during the final truss analysis and design phase.

After selecting configuration 6T/C as the best overall design, the final design phase was begun.

Using the preliminary design loads obtained from the NASTRAN model developed during the configuration selection phase, prototype longeron, diagonal, truss joints, and attachment joints were designed and fabricated. The specimens were designed by Bell Helicopter and fabricated by Brunswick. All specimens were filament wound on a break-apart steel mandrel and autoclave cured in order to achieve production representative properties. All specimens were fabricated using unidirectional Thornel 300 graphite in an LRF-092 epoxy matrix. In all, four different shapes were tested to determine column buckling design allowables. Test results are shown in Table 5.

Manufacturing considerations pointed to the Tee as being the most desirable cross-section for the frame and diagonal members. Member tests showed that they were indeed stable under compressive loads but that the dimensions should be changed in order to prevent local flange separation that occurred

A THE STREET STREET

TABLE 5. MEMBER COLUMN BUCKLING TEST RESULTS

TEST	MEMBER SHAPE	ρ (IN.)	LENGTH	P YIELD	P FAIL (LB)	AVG YIELD (LB)	FAILURE MODE
1	Square	.0817	16.5	1480	1530	1440	Column Buckling
2	Square	.0817	16.5	1400	1460	1440	Column Buckling
3	Channel	.0655	16.5	540	570	F 9 0	Flange Separation
4	Channel	.0655	16.5	620	660	580	Longitudinal
5	120° angle	.338	15.0	2100	2520	2250	Split in Web Longitudinal Split
6	120° angle	.338	15.0	2400	2770	2230	Longitudinal Split
7	Tee	.0926	8.0	4790	4900	4915	Flange Separation
8	Tee	.0926	8.0	5040	5150	4313	Flange Separation

NOTE: All specimens were tested as fixed end columns

$$\rho = \sqrt{\frac{I}{A}}$$

in all of the specimens. The only shape practicable for use in the construction of the longeron members was the 120 degree angle. All of these specimens failed due to a split down the center of the angle member. This indicated that the unidirectional fiber stacking sequence was providing an insufficient amount of transverse shear strength.

After reviewing the results of the 120-degree angle column buckling tests, it was decided to include several layers of 90-degree filament-wound T300 graphite cloth in the stacking sequence. While this design change meant that the truss could no longer be completely wound by machine, it was felt that the inclusion of the 90-degree fibers would yield a significantly stronger section. Schedule and budget constraints prevented the fabrication and testing of the new longeron sections. Instead, a NASTRAN model of the longeron was constructed. Using the test data obtained with the 100 percent unidirectional fibers as a baseline, the model was fine tuned to achieve compatible results. A mesh size of 6 x 56 was chosen to represent the longeron. This mesh size represents a set of 336 NASTRAN CQUAD1 elements each .25inch square. Element material properties were determined using Bell Helicopter composite material analysis program SC1701 (Reference 3). Program input consisted of the lamina stacking sequence and lamina mechanical properties as obtained from the material testing described earlier. As shown in Table 5, the average buckling load for the 120-degree angle test sections was 2250 pounds. The NASTRAN prediction for the failure was 2252 pounds.

Once the NASTRAN model was shown to be representative of the longeron structure, a new stacking sequence was input to program SC1701 to determine the laminate stiffness and bending maxtrix. These values were input to the NASTRAN model and a new buckling load was calculated for the longeron member. Several interactions were tried until a stacking sequence having the best strength-to-weight ratio was determined. The selected stacking sequence was optimized with 16 plys as (0, 0, 90, 0, 0, 0, 90, 0, 0, 0, 90, 0, 0, 0, 90, 0, 0).

Besides the individual member tests, member joint tests were performed to verify that sufficient capability exists to transfer loads among the members. The specimens were loaded in tension as shown in Figure 20.

THE WAY

Wilson, H.E., COMPOSITE ANALYSIS PROGRAM SC1701, Bell Helicopter Textron Report 599-162-927, April 1, 1977.



Figure 20. Member Joint Testing

Machined aluminum end fittings were attached to the constraint and load application members. These fittings were attached to the joint specimen members in double shear with a high strength epoxy bond. A single bolt hole was drilled in each fitting to provide for a pinned attachment. Before failure, the member joint was able to successfully transfer 150 percent of the maximum longeron load predicted by the design configuration study NASTRAN model (see Table 6). Failure of all specimens was a result of a compression failure in diagonal member 3 (see Figure 21). No spreading or ply delimination took place at the member joint of either specimen (Reference Figure 22).

TABLE 6. MEMBER JOINT TEST LOADS

Specimen	Longeron Load At Failure	Required Transfer Load*
1	6898	3950
2	5999	3950

^{*} Maximum longeron load obtained from joint out condition, design configuration study NASTRAN model.

A Commence




Figure 21. Member Joint After Testing




Figure 22. Member Joint Geometry

Fuselage-to-tail boom attachment joints were tested to verify fitting design and the fitting-to-longeron attachment method. The fittings detailed in Figure 23 were machined from hexagonal bar stock. They were attached to a sample longeron section with six protruding head rivets and a single layer of adhesive.

A 5/16-inch-diameter bolt was used to apply loading to the fitting. A fiberglass grip pad was built up on the other end of the longeron section. A tensile load was applied to the fitting. Test results are shown in Table 7.

Both specimens failed due to shear tearout at the bolt hole. This failure was directly related to the marginal e/D ratio provided by this design.




Figure 23. Machined Attachment Fitting

W. W. W.

TABLE 7. ATTACHMENT FITTING TEST RESULTS

Test Number	Failure Load	Required Load *	
1	5300	4600	
2	5500	4680	

^{*} Maximum bolt load predicted by design configuration study NASTRAN model for a joint-out condition.

Although this fitting design and attachment procedure provided a 13-percent margin of safety, it proved to be costly both in terms of manufacturing cost and in the calendar time required for fabrication. While the use of rivets and adhesive to secure the fitting to the longeron was a working solution, it was not altogether satisfactory. The single shear bond failed at 2120 pounds for specimen 1, and 2640 pounds for specimen 2. Careful examination of the specimens after failure revealed that a slight (<.01 inch) amount of movement in the fitting relative to the longeron was noticeable. This movement was due to a bearing failure around the rivet holes in the longeron member.

Based on the results of these tests, the attachment joint fitting was redesigned and the method of attachment to the long-eron was revised. Manufacturing cost and scheduling, and problems associated with obtaining hexagonal bar stock in a diameter required to produce a lug having a sufficient e/D ratio forced a complete redesign of the attachment fitting. The new design, as detailed in Figure 24, was constructed of 4130 alloy steel plate.

The angle was cold formed to fit the outside longeron contour. The face plate was cut from the same steel plate and welded to the angle. A 5/16-inch-diameter hole was drilled and tapped into the face plate. This allowed the attachment bolt to be positioned nearer the angle centroid since a nut bearing diameter and weld radius clearance did not have to be incorporated into the design.

Two additional attachment joint specimens were built and tested in order to verify the structural integrity of the welded endplate. Both specimens were loaded in excess of 200 percent of design load. No failure or material yielding was observed at this load level.




Figure 24. Welded Attachment Fitting

Two design changes were incorporated to alleviate the rivet bearing. First, the rivet diameter was increased from 5/32 inch to 3/16 inch. Second, two layers of fiberglass cloth were included in the longeron stacking sequence in the area of the attachment fittings. It was felt that the glass would provide a superior bearing surface than would the graphite by itself.

After analysis of the individual member, member joint, and attachment joint tests, design changes were incorporated into a second-generation design and an optimization analysis of the truss was begun. The design configuration study NASTRAN model was used as the starting point for the design optimization study. Being careful to stay within the design envelope of a 15-inch maximum diameter, the truss diameter, area and bending properties of the longeron, frame, and diagonal members were changed to develop the lightest structure possible while still maintaining compatability with the existing Model OH-58 tailboom stiffness. This optimization was done solely with a "try-and-see" approach. While this approach does not assure an optimum design, a weight savings of 2 pounds was realized when the weight of the truss boom is compared with the first 60 inches of an existing Model OH-58 boom. Additional weight savings could be realized if a tapered boom section were constructed. This approach was not considered for this program because of manufacturing considerations. Slightly more complicated tooling and winding computer programs would be required, but such a design could be readily produced in a production environment.

A weight comparison between the first 60 inches of the existing Model OH-58 boom and the three truss specimens is shown in Figure 25.




Figure 25. Truss Boom Weight Comparison (60 in. specimen)

The variation in weight between the three truss specimens was due to excess resin. The amount of fibers was constant in each specimen.

The final truss design (Figure 26) had an outside diameter of 14.50 inches and was 60.0 inches long, excluding the end fittings. Inclusion of the end fittings increased the overall length to 60.96 inches. The effective diameter as measured to the attachment bolt centroid was 13.4 inches.

The final NASTRAN model of the truss was constructed entirely of BAR elements. Complete moment continuity was assumed at each joint. Area and bending property values used in the model are shown in Table 8.

The model was fixed against translation at the forward end. Rigid (A = 2.0, I = 2.0) bars were connected to a mid-point grid established in the plane of the aft-most bulkhead. These bars were considered to be pinned at the truss frame. All loads were applied to mid-point grid and transferred to the truss structure by means of a shear distribution (Figure 27).

Output from the NASTRAN model consisted of the grid point displacement, forces and moments in each member, and MC/I + P/A stresses at 4 points on each member. NASTRAN was used to compare these calculated stresses with input allowables and to compute the margin of safety for each member.







Figure 26. Final Truss Design









NOTES:


- MATERIAL TO BE 1300 GARPHITE FIBERS WITH LAF OB2 EPOXT RESIME STRUCKING SEQUENCE: FROM 100 OF THE PROPERTY OF
- THICKNESS BUILD UP AT JOINTS AS REQUIRED
- 9 FROMES, LONGERONS, AND DIRGONAL MEMBERS ARE TO BE MOUND ALTERNATELY TO ACMIEVE AM INTERSPERSING OF FIBERS AT JOINTS

SECTION A-A
TYP LONGARON SECTION
SCREEN 1

209-038-158

TABLE 8. FINITE ELEMENT SECTION PROPERTIES

Member	Shape	Area (in. ²)	I ₁ (in.4)	I ₂ (in.4)	J _p (in. 4)
Longeron	Angle	.1957	.007946	.019372	.00001 (assumed)




Diagonal Tee .1347

.001896

.00322


.00001



Frame

Tee

.1203 .00113 .00316 .00001






Figure 27. Pinned End Rigid Bars

The design allowables were determined from NASTRAN models of the individual frame, diagonal, and longeron members. To ensure that the models used were representative of the actual structure, the individual member test specimens were first modeled. The finite element mesh size was then adjusted until the NASTRAN-predicted buckling load was compatible with the test results. Using the same mesh philosophy, models representative of the final member designs were constructed and run to determine design allowables. The NASTRAN predicted allowables for the various members are shown in Table 9.

TABLE 9. NASTRAN-PREDICTED MEMBER BUCKLING ALLOWABLES

Member	Shape	Length (in.)	Buckling Stress (psi)
Longeron	120° Angle	15	29539
Diagonal	Tee	16.5	24591
Frame	Tee	6.75	88637

Predicted member loading and the correlation to actual static stresses are presented in the Static Load Correlation Section.

FABRICATION

Once the final truss design was developed, work was begun on the tooling required for fabrication. First, a female truss pattern was machined on six wooden segments. The hexagonal shape was attained by assembling the six segments and securing them in place with two bulkheads (Reference Figure 28). outer shell for the sand casting was fabricated using six flat wooden pieces held in place by metal angles. The edges of these pieces were cut at an angle to form a tight hexagonal shape. A silicone rubber male pattern of the truss was cast between the wooden female pattern and the outer shell. This rubber pattern was removed from the wooden inner mandrel and attached to the outer shell (Figure 29). A metal wind axis was installed inside the mold, the interior was filled with a water soluable sand, and the assembly was oven cured. The wooden outer shell was removed after curing and the sand mandrel was exposed by peeling back the rubber pattern (Figure 30).

The sand mandrel was prepared for filament winding by taping all grooves with Teflon tape. A winding program developed by Brunswick Corporation was used to achieve an automatic winding sequence. First, the deep web grooves for the frame and diagonal members were wound. These members were wound alternately to achieve an interweaving of fibers. Once the deep web grooves were filled level to the lower surface of the sand mandrel, the longeron, frame, and diagonal flange winding was begun. As with the deep webs, the winding of the longeron, frame, and diagonal flanges was done on an alternate basis in order to achieve interwoven fibers at the member joints. All winding was accomplished with numerically controlled winding machines with the exception of the 90-degree ply fibers included in the longeron stacking sequence. These plys were laid up by hand.

Once the mandrel grooves were filled with the required number of pre-preg graphite fibers (Figure 31), the entire mandrel was wrapped in a highly absorbent cloth. The purpose of this cloth is to absorb the excess resin squeezed out of the windings during the cure cycle. Caul plates were then laid on top of the cloth, parallel to each member. These plates were secured with heat shrink tape. The entire assembly was then placed in a vacuum bag and autoclave cured.

After curing, the caul plates and cloth were removed and the sand mandrel was washed away from the truss structure. The truss was then cut to length. This step was necessary because of the fiber buildup at each end. This buildup was a result of the continuous fibers forming a closed-end loop as they reversed winding direction.

End fittings were attached with six NAS1738M6 "blind" rivets and an .01-inch layer of FM-123 adhesive oven cured at 250° F.



Figure 28. Wooden Tooling Pattern



Figure 29. Sand Casting Mold



Figure 30. Sand Casting




Figure 31. Wet Lay-Up

BALLISTIC TESTING

Ballistic testing was conducted at Fort Eustis, Virginia, during the week of 19 November 1979. The ballistic testing phase consisted of single shots at three different truss specimens. All specimens were loaded prior to ballistic impact. Specimens one and two were loaded with high-speed level flight loads while specimen number three was loaded with 150 percent of high-speed level flight loads. Loads were applied to the truss specimens using lead weights and a welded steel load application frame. This loading arrangement is shown in Figures 32 and 33.

The loads listed in Table 10 were applied at the free end of the tail boom specimens.

TABLE 10. SPECIMEN APPLIED LOADS

Test Specimen 1

$\mathbf{F}\mathbf{X} = 0$	MX =	3497*	inlb	(clockwise	looking	fwd)
ra - v	1.177 —	347/	TII TD	(CIOCVATSE	TOOVIIId	TM(T)

FY = 201 lb rt MY = 3131 in.-lb (comp on lower surface)

FZ = 417.5 lb down MZ = 14222 in.-lb (comp on RHS)

Test Specimen 2

FX = 0 MX = 2211 in.-lb (clockwise looking fwd)

FY = 201 lb rt MY = 3131 in.-lb (comp on lower surface)

FZ = 449.5 lb down MZ = 15312 in.-lb (comp on RHS)

Test Specimen 3

FX = 0 MX = 3300 in.-lb (clockwise looking fwd)

FY = 300 lb rt MY = 5066 in.-lb (comp on lower surface)


FZ = 675.5 lb down MZ = 28166 in.-lb (comp on RHS)

All moments taken about the center of the aft (free) bulkhead.

487

^{*} Lateral load was input a wrong W.L. attachment. Correct MX loading is 2211 in.-lb.

LEVEL FLIGHT LOADS APPLIED AT THE CENTER OF REAR PLATE.



LOOKING FWD

Figure 32. Truss Loading Diagram




Figure 33. Load Application Frame

The test plan for specimen number 1 called for ballistic impact to be at the center of the most outboard compressive longeron in the center of the second bay, B.S. 25.00 (see Figure 34).




Figure 34. Targeted Impact Area, Specimen 1

The round impacted a point below and aft of the target point, with the fuse being initiated by contact with a diagonal member.

Fragments destroyed the three tension side longerons and numerous diagonal members on the upper, lower, and exit sides of the truss. Figure 35, view looking inboard at the exit side of the truss, shows the fragment damage. Figure 36 shows the approximate amount of damage done to each member. The fraction shown by each member is the percentage of area damaged by the shell fragments.

The specimen continued to hold level flight loads for 30 minutes after impact.

Vertical deflections were taken immediately before and after ballistic impact, and in three 10-minute intervals after impact. These deflection measurements are shown in Figure 37. All measurements were taken from a point on the bottom of the load application frame to a fixed point on the ground directly underneath the measurement point.

The change in angle before and after impact can be calculated as

 $[\tan^{-1} (.375)/B.S. 60.00 - B.S. 25.00)] = .61 degree$

Even when the additional 1/8-inch creep deflection is included, the angle $[\tan^{-1} .5/35]$ of .82 degree is within the tail rotor driveshaft misalignment angle allowable of 1.5 degrees.






Figure 35. Exit Side Damage, Specimen 1

1.30

Darkened area represents amount of damaged material



View Looking Down



View Looking Right




Figure 36. Individual Member Damage, Specimen




Figure 37. Boom Deflection After Impact

The test plan for specimen number 2 called for the ballistic impact to be at the most outboard compression longeron/frame joint at B.S. 30.00.

The round impacted a point on the outermost compression longeron slightly aft of the targeted joint (Figure 38).

Fragments did not completely severe any of the longeron members but did completely destroy several diagonal and frame members (Figures 39 and 40). The back (exit) side of Figure 39 is shown in Figure 41. Figure 42 shows the approximate amount of damage done to each member. The fraction shown for each damaged member is the percentage of area damaged by shell fragments.




Figure 38. Targeted Impact Area, Specimen 2



Figure 39. Projectile Entry Hole, Specimen 2




Figure 40. Exit Side Fragment Damage, Specimen 2

1. N. C. S. C. S.




Figure 41. Exit Side of Entry Hole, Specimen 2

• Colored portion represents percent of damaged fibers



View Looking Down



View Looking Right





Figure 42. Individual Member Damage, Specimen 2

The specimen continued to carry level flight loads for 30 minutes after impact.

Vertical and horizontal deflections were taken immediately before and after ballistic impact, and in three 10-minute intervals after impact. These deflection measurements are shown in Figure 43. Vertical deflection measurements were taken from a point on the bottom of the load application frame to a fixed point on the ground directly underneath the measurement point. Horizontal displacements were taken from the vertical movement of the horizontal load application tray.






Figure 43. Boom Deflection After Impact, Specimen 2

Using a combination of vertical and horizontal deflections to calculate the change in angle after impact, the misalignment angle can be calculated as

$$[\tan^{-1}((.125^2 + .1875^2)^{1/2})/(B.S. 60.-0 - B.S. 30.00)]$$

= .43 degree

This value is well within the allowable tail rotor driveshaft misalignment angle.

The test plan for specimen number 3 called for the ballistic impact to be at the most outboard compression longeron/ frame joint at B.S. 30.0 (Figure 44).




Figure 44. Targeted Impact Area, Specimen 3

The round impacted the target area, completely destroying continuity between the frame, diagonal, and longeron members. The base fragment destroyed the majority of the outboard tension longeron/frame joint (Figure 45). Other longeron and diagonal members were blown away, indicating that multiple fragment hits may have detached some members from the structure. The most outboard tension longeron between B.S. 30.0 and B.S. 45.0 and part of the exit side frame at B.S. 30.0 appears to have been severed at both ends. These members were among those found several feet away from the test specimen. Both the upper and lower tension longerons were subjected to fragment damage. Figure 46 shows the upper tension longeron. The upper half appears to have been cut with a fragment, leaving the lower leg to fail under a tensile load.

Only the upper and lower compression longerons survived and retained the majority of their structural integrity after impact. These members could not support the applied loads and the truss collapsed immediately after impact.




Figure 45. Fragment Damage, Specimen 3



Figure 46. Upror Tension Longeron, Specimen 3

In general, the fragments passed through the composite members cleanly. Very little delamination was seen in the area surrounding a fragment hit. When delamination did occur, only a few plys on the exit side of the hole were affected. Cracks did not develop in the areas around the fragment puncture holes. An example of fragment damage is shown in Figure 47.




Figure 47. Typical Fragment Damage

Mark Street

STATIC LOAD CORRELATION

Each of the three specimens was instrumented with 12 strain gages. Readings were taken before and after ballistic impact. Tables 11, 13 and 14 show the correlation of NASTRAN-predicted strain with the measured values before impact.

TABLE 11. CORRELATION OF MEMBER LOADS BEFORE BALLISTIC IMPACT TEST 1

Gage No.	Member* ID	Measured** Strain ε in./in.	Predicted Strain ε in./in.	% Diff.
2	1	108	119	10
3	1	-167	-154	8
4	2	72	65	10
7	3	- 196	~199	2
8	3	-4 09	-262	36
9	3	-132	~14 9	13
10	4	170	192	13
11	4	142	190	34
12	4	217	205	6

Note: Pre-impact data not available for gages 1, 5 and 6.

Predicted strains at the gage locations were obtained by reducing the NASTRAN force and moment output data for the members of interest.

^{*} Reference Figure 48

^{**} Reference Appendix A, pages 86 through 95.




Figure 48. Strain Gage Locations, Specimen 1

Gage Set 4

W. Carlo

TABLE 12. NASTRAN MEMBER FORCES AND MOMENTS

	M _y (i	n1b)	M_z (i	in1b)	
MEMBER	END 'A'	END 'B'	END 'A'	END 'B'	P _X (1b)
			TEST 1		
1	-4.97	7	1.84	-5.23	- 322
2	.38	2	2.73	21	183
3	-9.39	-4.31	6.25	8.24	-500
4	10.54	. 95	-7.36	-1.88	723
			TEST 2		
3	7.62	2.7	2.51	-8.22	-1140
4	-2.63	.58	17.04	8.54	957
			TEST 3		
1	4.21	2.69	6.54	10.88	-549
2	-5.26	-1.43	- 7.79	-9.72	- 706
3	. 4	.1	8.01	11.3	-254
4	6.68	4.83	13.68	7.98	664

Using the forces and moments from the NASTRAN run shown in Table 12, the strain at the gage locations were calculated as follows:

ा सम्बद्धाः सुमृत्यस्य । १८८५ । १

Forces and moments are output from NASTRAN at the member end points. The gages were located approximately three inches from the 'A' end of the NASTRAN element. A straight line moment distribution was used to calculate the stress at the gage location. Axial force is considered to be constant throughout the length of the member (Figure 49).




Figure 49. NASTRAN LOADS, Member 1, Specimen 1

Looking at gage 2 (located on the outboard flange) the stress due to bending at the 'A' end is $f_b = \frac{M_C}{I_2} + \frac{M_C}{I_1}$

$$f_b = \frac{1.84(.24)}{.00322} + \frac{4.97(.1449)}{.001896} = 516 \text{ psi}$$

At end 'B'

$$f_b = \frac{5.23(.24)}{.00322} + \frac{.7(.1449)}{.001896} = -336 \text{ psi}$$

Using a straight line moment distribution between points 'A' and 'B', the bending stress at a point 3 inches from end 'A' is

$$516 - \frac{3}{8.25}(516 - (-336)) = 206 \text{ psi}$$

The stress at gage 2 is

$$\frac{P}{A} + f_b = \frac{322}{.1347} + 206 = -2184 \text{ psi}$$

Looking at gage 3 (located on the centerline of the lower web, the stress due to bending at the 'A' end is

$$f_b = \frac{-4.97(.2451)}{.001896} = -642 \text{ psi}$$

at end 'B'

$$f_b = \frac{-.7(.2451)}{.001896} = -.90 \text{ psi}$$

The bending stress at gage 3 is

$$-642 + \frac{3}{8.25} (-642 - (-90)) = -441 \text{ psi}$$

The stress at gage 3 is

$$\frac{P}{A} + f_b = \frac{-322}{.1347} - 441 = -2831 \text{ psi}$$

Using a material $E_{\rm C}$ of 18.37 (Table 2), the NASTRAN predicted strain for gage number 2 is

$$-2184/18.37 = -119 \mu in./in.$$

The predicted strain for gage number 3 is

$$-2831/18.37 = -154 \mu in./in.$$

Strains for the remaining diagonal members were calculated in a similar manner.



Predicted strain values for the longeron members were obtained as follows (Figure 50):




Figure 50. NASTRAN LOADS, Member 4, Specimen 1

At gage 10 (level leg, inboard), the bending stress at the 'A' end is

$$f_b = \frac{7.36(.495)}{.019372} - \frac{10.54(.226)}{.007946} = -111 psi$$

At end 'B'

$$f_b = \frac{1.88(.495)}{.019372} - \frac{.95(.226)}{.007946} = 21 \text{ psi}$$

73

Using a straight line moment distribution between points 'A' and 'B', the bending stress 5 inches away from point 'A' is

$$-111 + \frac{5}{15} (21 - (-111)) = -67 \text{ psi}$$

The stress at gage 10 is

$$\frac{P}{A} + f_b = \frac{723}{.1957} - 67 = 3627 \text{ psi}$$

At gage 11 (inboard gage on outboard leg), the bending stress at the 'A' end is

$$f_b = \frac{-7.36(.21)}{.019372} - \frac{10.54(.05)}{.007946} = -146 \text{ psi}$$

At end 'B'

$$f_b = \frac{-1.88(.21)}{.019372} - \frac{.95(.05)}{.007946} = -26 \text{ psi}$$

Using a straight line moment distribution between points 'A' and 'B', the bending stress 5 inches away from point 'A' is

$$-146 + \frac{5}{15}(-26 - (-146)) = -106 \text{ psi}$$

The stress at gage 11

$$\frac{P}{A} + f_b = \frac{723}{.1957} - 106 = 3588 \text{ psi}$$

At gage 12 (outboard gage on outboard leg), the bending stress at the 'A' end is

$$f_b = \frac{-7.36(.43)}{.019372} + \frac{10.54(.33)}{.007946} = 274 \text{ psi}$$

At end 'B'

$$f_b = \frac{-1.88(.43)}{.019372} + \frac{.95(.33)}{.007946} = -2 psi$$

At a point 5 inches away from point 'A'

$$f_b = 274 - \frac{5}{15}(274 - (-2)) = 182 \text{ psi}$$

The stress at gage 12 is

$$\frac{P}{A}$$
 + f_b = $\frac{723}{.1957}$ + 182 = 3876 psi

Using a material E_{t} of 18.88 (Ref. Table 2) the NASTRAN-predicted strain for gage 10 is

 $3627/18.88 = 192 \mu in./in.$

For gage 11

 $3588/18.88 = 190 \, \mu in./in.$

For gage 12

 $3987/18.88 = 205 \mu in./in.$

Strains measured in various members during tests 2 and 3 are presented in Tables 13 and 14 respectively. The NASTRAN-predicted strains for these elements were calculated in the same manner as shown on the preceding pages.

TABLE 13. CORRELATION OF MEMBER LOADS BEFORE BALLISTIC IMPACT TEST 2

Gage No.	Member* ID	Measured** Strain ϵ in./in.	Predicted Strain € in./in.	% Diff.
7	3	-519	-303	42
8	3	-316	-316	0
9	3	-449	-307	31
10	4	242	211	13
11	4	273	253	7
12	4	285	301	6


NOTE: Pre-impact data not available for gages 1-6.

75

^{*} Reference Figure 51.

^{**} Reference Appendix A, pages 96 through 105.

Figure 51. Strain Gage Locations, Specimen 2






Figure 52. Strain Gage Locations, Specimen 3

A Million .

TABLE 14. CORRELATION OF MEMBER LOADS BEFORE BALLISTIC IMPACT TEST 3

Gage No.	Member* ID	Measured** Strain ← in./in.	Predicted Strain ϵ in./in.	% Diff.
1	1	-225	-174	23
2	1	-307	-240	21
3	1	-319	-248	22
4	2	-422	- 337	20
5	2	- 277	- 267	4
6	2	-198	-259	31
7	3	- 199	-141	29
8	3	-72	- 67	7
10	4	138	191	38
11	4	242	282	16
12	4	380	302	20

NOTE: Pre-impact data not available for gage 9

The reason for the lack of better correlation was the large tolerances allowed for manufacturing. Tolerances of .01 inch were allowed for thickness dimensions while a .03-inch window was allowed for all length dimensions. A 15-percent increase in area can be obtained using the maximum dimensions rather than the minimum dimensions for a diagonal member. Minimum section properties were used for all members in the NASTRAN loads. Large dimensional tolerances were provided in order to hold down tooling costs. It was felt that these tolerances would not affect the evaluation of the truss for ballistic purposes.

^{*} Reference Figure 52.

^{**} Reference Appendix A, pages 106 through 115.

DYNAMIC LOAD IMPULSES

Strain gages were placed on members which exhibited the largest change in static load after elements were removed to simulate ballistic damage. It was felt that these members would also exhibit the largest dynamic impulse loads following ballistic impact. Continuous readings were taken starting approximately 4 msec before impact until the principal shock wave had passed the gage locations. Gage readouts are shown in Appendix A.

Analysis of the readout data revealed that the compression buckling allowable for both the diagonal and longeron members was exceeded by the dynamic impulse loads. Dynamic plus steady-state strain is presented in Tables 15 and 16.

No dynamic impulse information was available for test 3.

Investigation of the test specimens after ballistic impact did not reveal any damage that could be attributed to the impulse loads. The allowable tension strain (Ref. Table 2) was not exceeded. The compressive strain caused by the impulse wave traveled through the truss at a velocity that was faster than the reaction time of the structure. Thus, those elements subjected to a compressive impulse stress in excess of the design allowable did not buckle. It is felt that had a tension strain greater than the design allowable been experienced, failure would have occurred.

Contraction of

TABLE 15. DYNAMIC IMPULSE STRAIN (REF. APPENDIX A, PAGES 86 THROUGH 89)

Test 1

Gage Number	Member	Max Dynamic Strain µin./in.	Steady State Strain µin./in.	Combined Strain µin./in.	Design Allowable #in./in.
1	Diagonal	+ 640	N/A	640	9799
_	\	- 569	•	- 569	-1341
2	\	+1850	-108	1742	9799
_	\	-1317		-1425	-1341
3	\	+1424	- 167	1257	9799
	\	-1349		-1516	-1341
4	\	+1475	72	5147	9799
	\	-1106		-1034	-1341
5	\	+ 925	N/A	925	9799
	\	- 1174		-1174	-1341
6	\	+1104	N/A	1104	9799
	\	- 966		- 966	-1341
7	\	+1590	-196	1394	9799
	\	-1244		-1440	-1341
8		+ 394	-409	- 15	9799
	\	- 1907		- 2316	-1341
9	\	+1281	-132	1149	9799
	\	-1993		-2125	-1341
10	Longeron	+ 641	170	811	9799
	\				-1611
11		+ 712	142	854	9799
					-1611
12		+ 983	217	1200	9799
	\	- 605		- 388	-1611

TABLE 16. DYNAMIC IMPULSE STRAIN (REF. APPENDIX A, PAGES 96 THROUGH 99)

Test 2

Gage Number	Member	Max Dynamic Strain µin./in.	Steady State Strain µin./in.	Combined Strain µin./in.	Design Allowable µin./in.
1	Longeron	+ 890	N/A	+ 890	9799
	_	- 854		- 854	-1611
2	1	760	N/A	760	9799
	\	-1139	,	-1139	-1611
3	\	+ 880	N/A	+ 880	9799
	\	-1907	,	-1907	-1611
4	1	+1027	N/A	+1027	9799
-	\	-1466	,	-1466	-1611
5	\	+ 733	N/A	+ 733	9799
·	1	-1833	21, 55	-1833	1611
6	\	+1452	N/A	+1452	9799
•	\	-1797	,	-1797	-1611
7	\	430	- 519	- 89	9799
•	\	- 2135	313	-2654	-1611
8	\	0	-316	-2956	9799
O	<i>\</i>	-2640	310	2330	-1611
9	\	2053	-449	+1604	9799
9	/	- 852	~~**	-1301	-1611
	•	- 022		-1201	-1011

NOTE: Fragment cut sensor leads of gages 10-12.

The state of

CONCLUSIONS AND RECOMMENDATIONS

Analysis of the results of this study indicates that an open truss constructed of composite materials is a viable concept for a ballistically tolerant tail boom.

Use of filament winding techniques in the manufacturing phase demonstrated the manpower and time savings that could be achieved by using these techniques in a production environment. The use of a collapsible metal winding mandrel machined to close to tolerances would be needed to produce production quality parts of uniform weight and stiffness. Use of such tooling was not included in the scope of this program because of the extra cost involved.

Because of the openness of the truss, blast pressure did not play a part in boom damage after impact. A tearaway covering could be incorporated into future designs without reducing the ability of the truss to carry load after impact. The addition of such a covering would, however, eliminate the possibility of a round passing completely through the boom without detonating. The truss configuration tested had approximately 50 percent open area. Tail booms having a larger diameter could be designed with even more open area, thus increasing the chance for a complete miss.

Exit-side fragment damage was much more extensive than expected. Even though the truss design provided for approximately 50 percent open area, almost all members on the exit side suffered some fragment damage. A larger diameter truss would allow for more open area, thus reducing the chance that a fragment would strike a member. A larger boom diameter would also allow for the placement of more members outside of the fragment dispersion cone, thus reducing the chance for damage.

Fragment holes were clean cuts with only limited ply delamination on the exit side. No cracks were seen propagating from the holes. The unidirectional fiber orientation used in the fabrication of diagonal and frame members was satisfactory from a crack propagation standpoint. The brittle nature of graphite did not prove to be a cause of excessive member damage. It could not be determined from this program if cracks would develop in damaged members as a result of the continued application of level flight oscillatory loads. Fatigue testing of damaged specimens should be a part of any future program.

Dynamic impulse loads did not play a role in the truss design. Compressive strain caused by the impulse wave traveled through the truss at a velocity that was faster than the reaction time

of the structure and thus did not cause members to buckle. The high strength of the graphite provided a large margin of safety for any tensile impulse strains. It is felt that the addition of material in anticipation of dynamic impulse loading requirements is not necessary in future designs.


REFERENCES


- 1. ADVANCED COMPOSITE DESIGN GUIDE, Rockwell International Corporation, Contract F33615-74-C-5075, Air Force Flight Dynamics Laboratory, Air Force Systems Command, Wright-Patterson Air Force Base, Ohio, April 1976.
- McCormick, Caleb W., NASA SP222(03) NASTRAN USER'S MANUAL, National Aeronautics and Space Administration, Washington, D.C., July 1978.
- 3. Wilson, H. E., COMPOSITE ANALYSIS PROGRAM SC1701, Bell Helicopter Textron Report 599-162-927, April 6, 1977.


Contraction of the same

APPENDIX A COMPOSITE TRUSS TAIL BOOM TESTS


This appendix contains the measurements of the composite truss tailboom tests.







THE ROLL



Company.

BTRACS (9 Nov. 78 Composite Trus Tail Storm Tests Shor 1, Boom 1, 5, Cage Cat Steps 170 - 2347 170 = 2420 16D = 2420 170 = 2420 17D = 2420 3 8 द्ध 862 366 SG3


*

867								1	
75	17.5D =	2420							
		{		***************************************	-	***************************************		****	And the second
		<u> </u>	16.5D = 2420						
858									
658				(7D = 2420					
SG10					176 - 2420				
\$611						170 = 2420	420		
SC13						}	160	165 - 2420	
			Ž	Note: All Values	un/lun #		BTRACS TO COMPOSITE Shot 1, Box	Truss Tall 8	BTRACS 19 Nov 79 Composite Truss Tall Boom Tests Shot 1, Boom 1, S. Gege Cal Steps


· • • • • • • • • • • • • • • • • • • •								
Zaro	Preshot				Post-shot	Pos	Post-silor 2	Post-shot 3
SG1			463	391	44		8	175
		L						
\$62	3	}	343	307	325		325	343
	108							
863								
	167.		Vortes: All Va	600 Notes: All Values = µ in./in.			883	
			+ + Co	Tension = + Compression = +		Comp Shot	CE 19 Nov 78 esite Truss Ta	BTRACS 19 Nov 79 Composite Truss Tail Boom Tests Shot 1, S. Gage Linny Period Data
• • •			No Ti	No Time Base Measured				


· · · · · · · · · · · · · · · · · · ·								
Zero	Pre-shot.	22	Impact	Frag Cable Cut				
Zero	Pre-shot	Impact			Post-shot. 1		Post-shot 2	Post-shot 3
						104 Comp	ક	
		}						
			oces; All	298 Notes; All Values = μ in./in.		5	8	X
			_ → %	Tension = + Compression = - No Time Base Messure	7	Shot 1	BTRACS 19 Nov 79 Composite Truss Tail Boom Tests Short 1, S. Gage Loni Period Data	Boom Tests Period Data


BELL HELICOPTER TEXTRON FORT WORTH TX CONCEPTUAL DESIGN OF A "HELICOPTER COMPOSITE TRUSS TAIL BOOM.(U) APR 80 D A GALLTAN DAKK51-78-C-0016 F/G 1/3 AD-A085 132 UNCLASSIFIED USAAVRADCOM-TR-80-D-8 NL 2:2 END 7 80 DTIC




196 196 197									
196 292 409 392		Present							
Impact						Po		Post-shot 2	Post-shot 3
Impact BOS B		86		392			•	382	282
Impact B05 559 569 100 1									
Impact B05 5589 5589									
			Tunect						
		La termone							
Impact 578 578 Tension = ± Chapterion = ±		8		B05			269	. 20	100
Impact 578 578 Tension = ± Compression = ±	• - • •								
Impact 578 578 Tension = ± Chapterion = ± Wo The Base Mean of									
Notes: All Values = # in /in. 529			Impact						
		133		578		529		529	23
								· · · · ·	
				DIEK. WII VAID	10 Tu 10 Tuu.		A 0 + 0	44 CF 94	
				Tons	## 46		Comp	site True Tell	Boom Tegg
					premion = -	1 1	5		Lenod Lan
				No Tim	Base Metaure	+ + + + + + + + + + + + + + + + + + + +			













70 P 30




	- :		: ::::::: !	ПППП	11111		8 5
· · · · · · · · · · · · · · · · · · ·	123						BITMAS 20 Nov. 79 Composite Trus Tail Boom Tark Shor 2: 5. Gage Long Ferror Data
			2		1		2 P
3				1 1 1 1 1 1 1 1 1	· · · · · · · · · · · · · · · · · · ·		0 = P
	:				}		
1 5 6 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	9		98				2 5 5
4							7 5 9
- B							E 5
	::: ! :						ಷ ರ ಹ
					: : : : : 		
					· · · · · 		
ost-shor	2		8		::::: {		
					: : : : !		
					: : : : :		
	1					::::	
	<u>.</u>				1 1 1 1 1		\$
	. }				11111	<u></u> 10	
	8		8			Notes: All Values = µ in./in Tension = +	Compression =
	7		· · · · · · · · · · · · · · · · · · ·		:::: }		3 5
			y		m Dect		
	1		d d		<u>E</u> {	a)	
	Impaci						
	Ε	İ					
		}					
		}					
· · · · · · · · · · · · · · · · · · ·						+	
• • · •							
	'	}					
· · · · · · · · · · · · · · · · · · ·		}					ļ
	2	<u> </u>		. :			
	Zero			a a			
	SGI	1.	23	j	g	•	

1			
Post-shot 3	77.	22	Boom Tests g Period Dena
Port-shot- 2		8	BTRACS 20 New 76 Compatite Truss Tall Boom Tests Shot 2, 5, 0 age Long Period Data
		202	
Post shot			
		22	on = + in/in.
	7		Note: All Values = #
100 H		Шрес	<u>}</u>
Par A			
Zg4	1	926	



	T:::::::::::::::::::::::::::::::::::::			
				BTRACS 20 Nov. 79 Composite Truss Tail Boom Test Shot. 2, 5. Gage Long Period Data
				Fig.
 				<u> </u>
		}:::::::		2 2 9
				10 ss ag
				0 ± 0
			tmp&ct	8 2 2
+++++	 - - - - - - - - - -	 		STO.
• • • • • • • • • • • • • • • • • • •	1	· · · · · · · · ·	2	
·	\frac{\frac{1}{2}}		S	
	Pre-sho	<u> </u>	1	
	4			
• • • • • • • • • • •				
	\ \			· · · · · · · · · · · · · · · · · · ·
				1 + 6
				1
* • • • • • • • • • • • • • • • • • • •				All Values = µ in/in.
				₹ + - 2
: : : : : : : :				
				Notes:
1	1::::			
	 			
· · · · · · · · · · · · · · · · · · ·				
• • • • • • • • • • • • • • • • • • •				
• • • • • • • • •				
• • • • • • • • • • • • • • • • • • •	1:1:1:1			
	1::::			
• • • • • • • • •	25			
	1			
	8610	#88	\$612	
	ો .છ.∤	1 	[




SG6 SG6 SG6 SG6 SG6 SG6 SG6 SG6	Sense **Sense **Compression = *** **Compression		-							
See 1 Territoria 1	Notes: All Values = p. In./fn. Timpion = **				-	4	•			
Some Some Some Some Some Some Some Some	# Same **Compression : **Compression : ** ** **Compression : ** **Compression : ** ** **Compression : ** ** ** ** ** ** ** ** ** *									
346 1. Same Motes All Value = 1 In the Nation	Notes: All Values = p. in./n.									
346 Note: All Values # Information # 1 Compression # 1	3.06 Note: All Values = Infilm Base: Temion = 1	•				1	:		+	
23.6 23.6 1. Same 1. Same 1. Compression :	1. Some									
1225 12 Same 12 Same 13 Same 14 Same 15 Compression = 1	2.6 Compression :					• • • • • • • •				
29.6 12.5.0.0 13.5.0.0 14. Compression = 1.	236 336 336 346 356 366 376 376 376 376 376 376 376 376 37									
1 Some All Value = μ in.l.f	T. Same T.									
1. See 1.	Some 1 Some 1 Conformation = 1 1 Conformation = 1		11783							
1. Compression = 1. Co	Some And Wilder Hilliam Bush		_	-						
33.6 14 Same 15 Same 16 Same 16 Same 17 Terraforr 1 Compression = 1	Same Same **Same **Notes: All Values = #:in./in. Terralogn = + Compression = + Compression = +	8 2								
See 1 Tring Base: Notes: All Values = p. in./in.	# Seese 686		7							
See	See								: : : : :	
1 Somi	See									
Some Some State St	Notes: All Value = µ. in./in. Tendon = +									
1. Same 1. Same 1. Same 1. Same 1. Terration = +	See 15 See 1									
2.06 1. See 1. Inv. Busin. 1. Terration = .+ Compression = .+	Same Same Same And Best And Best Tempore All Values = 4 in/fin Compression = 1 Compression = 1	•				:				: : : : : : : : : : : : : : : : : : : :
346 1. Same Notes: All Voltes: All Voltes: A in/in. 1. Temprore + 1. Compression =	246 1 See 1	-								
1 See	See 226 See									
Some 15 Some 16 Some 16 Some 17 Terrelogie = 1. in./in.	15 Sense 18				•					:
Sone **Sone **Sone **Notes: All Values = # in/in. Terrator = # Compression = # Compressi	15 Some Notice: All Values = µ. in./in. Terrators = 1									
# Sense # Sense # Sense # Sense # Notice: All Values = p. in /in. Tension = +	15 Some 1664 17 Some 18 Some 19 Some 10 Terrafor = + 1 Compression = +			-						
# Some ** Some ** All Value = μ in /in. ** Notes: All Value = μ in /in. ** Compression = +	15 Sange	SG5	346							
14 Some Notes: All Values = # in/in. Templon = **	Some Notes: All Values = \(\mu \) in/in.		-							
15 Sense 15	Notes: All Values = # Invita				•					
15 Sensor	15 Series 16.04 16.04 17.04 18.04 18.04 19									
15 Sones 1694 1694 17 Sones 18 Sones 19 Sones 19 Sones 19 Sones 19 Sones 10 Sones 11 Sones 11 Sones 12 Sones 13 Sones 14 Sones 15 Sones 16 Sones 16 Sones 17 Sones 17 Sones 18	* Serve ** Serve ** Serve ** All Value = # Ind/In. ** Profee: All Value = # Ind/In. ** Compression = **						•			•
# Some Compression = +	# Sense # Sense # Compression = + Indian		-							
# Sense: Notes: All Value = # in/in.	# Some									
# Some # Some # Some # Some # Notes: All Values = µ in /in, # Compression = +	# Series ** Series ** All Values = # Invilin. ** Notes: All Values = # Invilin. Temfort = # Compression = #		-						T	
# Sense # Sense # Sense # Sense # Motes: All Values = \mu \intinuntum # Temfor = #	it Sames Notice: All Values = \(\pi \) in /in.	-	-							
* Some ** Some ** Notes: All Value = # in/in. Tenion = #	# Some **Notes: All Values = # in./in. Temson = **									
15 See 15 All Values = 1 In All All All All All All All All All Al	# Some All Values = # inv/in. Notes: All Values = # inv/in.									
15 Sones 16 Sones 17 Sones 18 Sones 19 Sones 19 Sones 10	** Sense: **All Values = #. In /In. **Notes: All Values = #. In /In. **In Tendor = #.	956	5							. 1
Notes: All Values = p. in/in.	Notes: All Values = p. in / in.	200		-						
Notes: All Values = #. in/in. Tension = +	Notes: All Value = µ in/in. Temson = +		 }							1 1
Notes: All Values = µ in/lin.	Notes: All Values = p. invlin.									
Notes: All Values = µ in /in.	Notes: All Values = p. in /in. Tension = +			-			:			
Notes: All Values = p. in/in.	Notes: All Values = µ in/lin.									
Notes: All Values = # in/in. Tension = +	Notes: All Values = µ in /in.			-					† !	+
Notes: All Values = µ in /in. Tension = +	Notes: All Values = µ. in/in. Temion = +									
Notes: All Values = \mu \in/in.	Notes: All Values = µ. in./in. Tension = + Compression = +		<u> </u>							-
Notes: All Values = µ in /in, Temion = +	Notes: All Values = μ in/lin, Temsion = +	Hapact Vanes	=			1 1	+ + + + + + + + + + + + + + + + + + + +			
Notes: All Values = µ in/in, Tension = +	Notes: All Values = µ in/in, [Terrafor = +					ZO 48 MSec Time	Bee			
Notes: All Values = µ in./in. Temion = + Compression = +	Notes: All Values = # in/in, Î Temion = + Compression = +							1		+
Î Temson = +	Compression				1	/alue = 4 in/in.				
Î. Temion ≈ + Comprestial = +	Tension = +		}						100	
Compression = -	Compression = -						:	****	3 3 3	
1 Compression = 1	Compression					Enston # +		S	osite Truss Tail	Boom Tests
Compression F.	Compression = -							100	A.S. Gara Dan	
		•			0 :- · · · · · · · · · · · · · · · · · ·		:			

8

89

25

9510 9511 9522 9512 9512 9512 9512 9512 9512 9512 9513 9514 1 Trainion + 1 Trainion											
Series Se		:	:	• • • • • • • • • • • • • • • • • • • •							
Sense Sense Notes: All Value = # in.fm. Terision = + Compression = +	• • • • • • • • • • • • • • • • • • • •					:					
Serie Serie Notes: All Values = µ In Jn. Terridon = + Terridon = + Compression = -											
Serve Serve Notes: All Volume = # in.fm. Notes: All Volume = # in.fm. Compression = +											
Series Se					+						:
Sense (697) Sense (697) Sense (697) Motes: All Value = µ in /m. Compression = + Compression = +				•							
Serve Serve Notes: All Velues = # in.fm. Compression = +	\$610	415		· · · · · · · · · · · · · · · · · · ·							
Some Series (Some All Value = \mu in Jfn. Tension = \mu in Jfn. Tension = \mu in Jfn.	-										
522 522 687 6887 Contract All Value = \(in											
CSG.	•	•		•	!	!					
Serve Serve Compression - Compression - Compression -											
C Simp											
822 (Sarae 1 Sarae 1 Sarae 1 Sarae 1 Sarae 1 Sarae 1 Tarison = + 1 Compression = -	•				•						:
C. Some 1. Some 1. Some 2.048 MSec 1 im Base 1. Tension = + 1. Compression = -											
Sanse San											
Series Carting Base - 2048 MScc Time Base - 1 fersion - + Tersion - + Compression Compression											
Compression - Co		-		-	•						
Series (587) 1 Series (587) Notes: All Values = \(\mu\) in Jin. 1 Tension = + Compression			:		:						
CSONS (SSONS) Notes: All Value = # in/in. Terision = + Compression = + Compr											
1 Sense 1 Sense Notes: All Values = µ in/In. 1 Tension = + 1 Compression =		622			•						
t Sonse 1 Sonse 1 Sonse 1 Sonse 1 Sonse 1 Terision + Terision + Compression - Com	\$611	-	-	-	•						
t Sense 1 Sense 1 Sense 2048 MiSc Time Bees 1 Invin. 1 Tenson = + 1 Compression = +	***************************************		-								
C. Some I. Some Notes: All Values = µ In./In. Tension = + Compression = +											
t Sense 1 Sense 20,48 W.Sec Time Base 1 Tension = + 1 Compression = +											
t Some 1 Some 20/48 MiSoc Tune Base Notes: All Values = \(\mu\) in./in.											
t Sense 1 Sense 20048 MSec Time Base Notes: All Values = # in/im.			-								
f. Sense Notes: All Value = # in./in. Tension = + Compression = -											
f. Sanse (* Sanse) (-							
t Sense 1 Sense 20/48 MSec Time Bess Notes: All Values = \(\mu \) in /in.											
t Sense 2048 MSec Time Base Notes: All Values = # in/in.		_		-							
t Sanse C Sonse C S											
1 Sense 1. Sonse 20 dB MScc Time Bese Notes: All Values = \(\mu \) in /in.	5012	1587									
Notes: All Values = \(\mu\) in /in.	71.8	3									
Notes: All Values = µ in/in, Tension = + Compression = -			•								
Notes: All Values = \mu in_in.		-									
Notes: All Values = µ in Jin. Tension = + Compression = -											
Notes: All Values = \mu in./in. Tension = + Compression = -	•										
Notes: All Values = μ in Vin. 1 Tension = + 1 Compression = -			-								
Notes: All Values = μ in Jin. Tension = + Compression = -				•							
Notes: All Values = \(\mu \in \in \in \). Tension = + \(\tau \text{Compression} = - \)											
Notes: All Values = \mu in./in. Terison = + Compression = -											
Notes: All Values = μ in /in. Tension = + Compression = -					:		:				
All Values = μ in /in. † Terision = + Compression = -					1 :						
All Values = μ in /in. Tension = + Compression = -						7	DAB MSec Time	Bess			
All Values = μ in /in. 1 Tension = + + Compression = -				-	•						
Tension = +					2		unes = 4 in /in.		AGTO	C 21 Na 7	9
, II. + 5	==	}			-						Door Tark
, , , , , , , , , , , , , , , , , , ,						+	+ 11 50		3		
pression = -					•				Tors.	3, S. Cage Dat	
				•		÷					
		•				\$					



N. Spaces	5		Zéro Præ-load Strain	s ≡ μin/fm.	Compression = Compression = Composite Truss Tail Boom Tests Shot 3, S. Gage Long Period Data Random Time Base
			Zero		

		1	:	:	:	•						•										•	•					-,		•			-	-	-			· ·	•	-	-				•	:	•						1	,	•					:	•			*	•	2				:	-
:				1	:								:				:			:		•	•	•		1					:																						:	:	•						•			7	i	whore us us dage tong Period Date				•	
	<u> </u>	:	:	+	+	1			: 		· •	:	,		-				•		-	•	·		1			- •	_	•	•	1				-	. -					•	1		•						_	-	•	•	· -		-		•	:	• •	2	į.	2	{ !	E	•		•		
	•	•	•					Ę			•								•	•				•		3		Damaged																										•	•							2	\$	1	; 	2	r	•			
		:		-								- -					:						_			#4			_	-			Ε.			· •		_	_	_	-			_									:		•							24	2	1		5					
		:		•													•						:						•																			-														VEL				e E					
			:	•									:					:		•			:	•		•											÷											3		Ter									•	•	•		,	U	, 6						
	•	:	:	:	:			_			Ĕ			2	}		-		•	•	-	•	-			•	-		-				S				•		-	-				_	-	•	Ç	}	_ {	Pre-load Strain		+	•	-					:	:		-	-	<u>-</u>	-	-		•	-	•	<u>.</u>
		•									E				:}																	7															ř	5		Pre-																					
	:	:	•			-	-	-		-			•		-						+	· -	•		•					•		-	1	-					•••									· •	7	ļ 		-			-		:	· 	•		:	-		-		:		:	:	:	
			:												i					:																				:				:	:										•				u Vin		:				. #	- .			:		:
		:	:	:									•		-					•					•								-											:	:										•				7 1		:	+ * E			COLUMN	į					•
			:	•		•				ľ		•			- 1	ŀ				•		•	•				-•													:			1	:	•	•							•		-				Att Value = u in /in			- ension				I Distance Letters		Anna Times		:	•
																																																						•	•						*			-				á	2		
	-		· •	•		•				-	-		-		_	ĺ		-	•	•	1			•	•					•		+					:	•	:		•		-		· • •				-			-			:							-		-		-		• • •	• •-	•	:
		•	:	:								•	•			Ì				•										:														•	:			•								•			•	:				•	•						
	•	:	:										:		i	}	-				1	•			•							-					:	•				-	-								Zero					•		•			•										
																}		•																										•					1																						
		•	:													ļ			:				•			•	٠				•																		}																			•			
		:	:	:	- • • •		_			-			•		1	Ì					+		-	-			_			•	•	1				•		•			_	•	1	_	•	•	_							-	•	-		-	_	-		1	-	• •	-		-	-	•	•	•
						•														•													į												_	-										_		Ξ.									_	•••			-
-		•	:				_		•	-	760	7		-		į		-	•		-	•	•	•	-		-						-										1	٠								-								-				•			•				
				:							•			٠		į																											1																												
												•		9	3	}																4	3										1					60.13	3																						

-								
						• • • • • • • • • • • • • • • • • • • •		
				The second secon	-	-		
-	350 = 2420							
198								
	₹	1			-			
	:	36.60 = 2420	20	:				
							:	
	-							
202]	ş	-	*************	-	Annual Control of the	***************************************
			38D	2347				
		,		:::::::::::::::::::::::::::::::::::::::			•	•
•								
Q Q								
200			_					
				Į	1.			
				330	D = 2420			
758	•							
		-		7				
					יי			
						30D = 2420		•
					-			
SG5								
							25 RD = 2247	47
								!
208								* * * * * * * * * * * * * * * * * * * *
				+				1

		2	Notes: All Values = # in./in.	* = # in./in.				
			1					
			Cisus	+		BIRA	S ZI NOV Z	
							Composite Trus Tail	
			Comp	region = -		10/A	L. S. Gogs Lor	9 Period Date
			+		1			

		36.5D = 2420	18							
267										
808 808			, , , , , , , , , , , , , , , , , , , ,	33.5 - 2420	2420					
898						350 × 2347				
SG10						380	= 2420			
3611								360 - 2480		
\$612									ak D	185
				2	olgs: All VA	All Values = µ in./fn.				
					Con	Tension + +		BTHACS Composit	7 E 3	Now 79 sr Tall Broom Tests F. Lovy Period Dens